



Digital Max Min Thermometer

Specification:

- Measurement Range:** -10 to 50°C&F
Accuracy: +/-1°C
Display Resolution: +/-0.1°C
Sampling Rate: 10 seconds
Battery: 1.5 volt (AA) x 1 piece


Remove the battery cover and insert the AA battery supplied. The thermometer should be positioned away from direct sunlight and draughts to ensure an accurate reading.

The minimum reading indicates how low the temperature has dropped and the maximum reading indicates how high the temperature has risen.

The current temperature is displayed in the center of the instrument.

To reset the readings, press the CLEAR button.

To switch Celsius to Fahrenheit, press C/F button.



Brannan Thermometers
Cleator Moor Cumbria
England
www.brannan.co.uk